

FIG.1A

BEFORE LOADING INTO ANNEALING FURNACE




FIG.1B

HEAT-UP STAGE




FIG.1C


REACHED ANNEALING TEMPERATURE,  
FOLLOWING COMPLETION OF HEATING UP

FIG.2




FIG.3




FIG.4




FIG.5




FIG.6




FIG.7




FIG.8


RELATION BETWEEN MIXING RATIO OF HYDROGEN GAS AND  $C_S/C_B$ 

FIG.9

